

MINE INSPECTION REPORTS 1st Q 2017

Quarter inspections 2017

OAKTOWN FUELS #1, SUNRISE COAL

Inspection date(s): 1/5/17

Areas Inspected: Unit 3, belts

Findings/Law Violated:

1. Miner #14 left side unit 3 cable run over. 30cfr 75.606
2. #8 roof bolter no pry bar. 30cfr 75. 211(d)
3. Belt master cable in contact with hi voltage cable M71st left. 30cfr 75.807

Corrective action taken: all violations corrected

Inspection date(s): 3/23/17

Areas Inspected: unit 4, belts

Findings/Law Violated:

1. Oil leak on #10 roof bolter at face. 30cfr 75.400

Corrective action taken: corrected leak

OAKTOWN FUELS #2, SUNRISE COAL

Inspection date(s): 1/19/17

Areas Inspected: surface, shop, plant, belts, tunnels, train load out

Findings/Law Violated:

1. Head of slope belt mine 1 walk way needs cleaned. 30cfr 77.205
2. Fire extinguisher in draw off tunnel out of date. 30cfr 77.1110
3. Raw coal reclaim feeder 109 d needs ID 30cfr 77.809
4. Fire extinguisher on 1st floor of plant out of date. 30cfr 77.1110

Corrective action taken: violations noted and corrective action taken.

Inspection date(s): 2/1/17

Areas Inspected: unit 3, belts, intake

Findings/Law Violated:

1. No violations

Corrective action taken: none

CARLISLE MINE, SUNRISE COAL COMPANY

Inspection date(s): 1/18/17

Areas Inspected: surface

Findings/Law Violated:

1. Fire extinguisher no tag at fuel station pump house. 30cfr 77.1110
2. Need to clean {clean coal draw-off tunnel. 30cfr 77.202
3. Need to clean sample house for clean coal. 30cfr 77.202
4. Need to clean walk-way for clean coal belt. 30cfr 77.202

Corrective action taken: all violations noted and corrective action taken.

Inspection date(s):

Areas Inspected:

Findings/Law Violated:

1.

Corrective action taken:

FRANCISCO MINE, PEABODY COAL

Inspection date(s): 1/25/17

Areas Inspected: surface, plant, belts, & tunnels

Findings/Law Violated:

1. Clean belly pan for unit 102 refuse collecting belt. 30cfr 77.202
2. Raw coal over-land belt stacker walk-way needs cleaned. 30cfr 77.205

Corrective action taken: violations noted and corrective action taken.

Inspection date(s): 3/20/17

Areas Inspected: surface, books

Findings/Law Violated:

1. No violations

Corrective action taken: none

FREELANDVILLE WEST, TRIAD COAL COMPANY

Inspection date(s): 1/6/17

Areas Inspected: surface

Findings/Law Violated:

1. No violations

Corrective action taken: none

FREELANDVILLE MINE, TRIAD COAL COMPANY PREP PLANTS #1& #2

Inspection date(s): 3/2/17

Areas Inspected: surface, plants, belts, equipment

Findings/Law Violated:

1. No violations

Corrective action taken: none

GIBSON MINE, GIBSON COAL COMPANY

Inspection date(s): 2/21/17

Areas Inspected: surface, belts, tunnels, shops, silos, plant

Findings/Law Violated:

1. Rotary breaker fire extinguisher missing a tag. 30cfr 77.1110

2. Need to clean tail of over land belt. 30cfr 77.202
3. Bad bottom roller inby opening to draw off tunnel. 30cfr 77.404(a)
Corrective action taken: all violations noted and corrective action taken.

RECOMMENDATIONS:

GIBSON MINE, SOUTH

Inspection date(s): 1/9/17

Areas Inspected: surface books

Findings/Law Violated:

1. No violations

Corrective action taken: none

RECOMMENDATIONS:

Inspection date(s): 2/13/17

Areas Inspected: unit 3,intake, belt

Findings/Law Violated:

1. No curtain in the x cut #81 and the face of same entry. 30cfr 75.370(a)(1) over 1%ch4 in the face of entry.

Corrective action taken: curtain was installed and violation corrected.

Inspection date(s): 3/3/17

Areas Inspected: surface

Findings/Law Violated:

1. Need ID on breaker in warehouse. 30cfr 77.809
2. Need to clean tail of roller of the B belt plant feed. 30cfr 77.202

Corrective action taken: corrected

GOLD STAR MINE

Inspection date(s): 1/30/17

Areas Inspected: surface, books

Findings/Law Violated:

1. No violations

Corrective action taken: none

Inspection date(s): 2/10/17

Areas Inspected: intake, secondary, seals, surface

Findings/Law Violated:

1. Fire extinguisher on #5 mini-trac out of date. 30cfr 75.1100-3
2. Scoop charger #4 needs proper ID. 30cfr 75.809
3. No ball on life line in intake at #6 x cut. 30cfr 75.380-7(vi)
4. Need a new tag on fire extinguisher at power center. 30cfr 75.1100-3
5. Fire extinguishers at fuel station are out of date. 30cfr 77. 1110

Corrective action taken: all violations noted and corrective action taken.

LOG CREEK MINE

Inspection date(s): 1/24/17

Areas Inspected: books, surface

Findings/Law Violated:

1. No violations

Corrective action taken: none